

Nepshaw Lane South, Morley, Leeds, LS27 7JQ Materials Testing Manager: D. J. Brockbank t: 0113 393 9791 e: dale.brockbank@wyjs.org.uk www.wyjs.org.uk/materialstesting



**TEST REPORT** 

Client:	AB Ludvig Svensson Bangatan 8 SE-511 82 Kinna Sweden
Entry No:	89982
Date received:	11/09/2017
Client's Description:	Sample of fabric: Pond
Test Required:	Flammability BS 5867-2: Type B
Pre-treatment:	None
Conditioning:	A minimum of 24 hours at 65+/-5% Relative Humidity, 20+/-2°C
Date Tests Completed:	18/09/2017
Method of Test:	BS EN ISO 15025: 2002 Procedure A (surface ignition)

The results may not apply to situations where there is restricted air supply or prolonged exposure to large sources of intense heat as in a conflagration.

## Flame application time 15 seconds using propane gas

Face of Fabric tested	Fabric length direction			Fabric width direction		
Specimen number	<b>1</b> ↑	2↓	<b>3</b> ↑	<b>4</b> →	5←	<b>6</b> →
Flame reached an edge (✓ or X)	X	Х	Х	X	Х	Х
Hole reached an edge (✓ or X)	X	Х	Х	X	Х	Х
Flaming debris (√or X)	X	Х	Х	X	Х	Х

## Comments

On the basis of the tests carried out this sample of fabric meets the Type B requirements of BS 5867-2: 2008.

-----End of Document------

This is hereby certified to be a correct return of the tests made of the items referred to herein

Dale Brockbank Materials Testing Manager 18 September 2017

• Unless instructed otherwise by the client sample remnants will be disposed of after 28 days.

Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.

Uncertainty budgets for test methods contained within this report are available on request.

This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.



